

Lessons Learned Database

Individual Incident Summary Report



Incident Title		Polyethylene Dust Explosion	
Incident Type		Dust Explosion	
Date		29 th January 2003	
Country		USA	
Location		Kinston, NC	
Fatalities		Injuries	Cost
6		38	Unknown
Incident Description	An explosion and fire occurred at a plant producing rubber drug-delivery		
	components (e.g. syringe plungers, vial seals, septums etc). The semi-		
	continu	ious manufacturing process involv	ed compounding batches of rubber
ALL ST THE FALL	in mixe	ers, rolling them into strips, and th	en either moulding them on site or
ALL AND	shippir	ig them off site. To reduce the stic	ckiness ("tackiness") of the rubber,
	the roll	ed strips were first conveyed throu	gh a tank containing a slurry of very
	fine po	lyethylene powder in water ("anti-ta	ck ² agent). The coated rubber strips
	were tr	ien air dried with fans. The explosition	on occurred abruptly with while the
Credit: US Chemical Safety Board	piant w	ding firefighters) were injured and	s were killed, so more (including 2
Incident Analysis	Basic cause was accumulation of fine polyethylene dust above a suspended		
Incluent Analysis	ceiling in the production area which somehow became dispersed creating an		
	explosive mixture in a confined space which then exploded		
	Critical factors included: 1) Polyethylene dust was not identified as a		
	combustible material on the MSDS, 2) The room containing the rubber		
	compounding process had a suspended tile ceiling and a comfort air (HVAC)		
	system that drew air through the ceiling, 3) Small amounts of polyethylene		
	dust will have become airborne as the rubber strips were blown dry, 4) Dust		
	removal from hidden surfaces in the production area (e.g. above suspended ceiling) was not part of the permanent cleaning crew's housekeeping activity		
	5) Electrical fixtures and wiring in the production area were not Ex rated 6)		
	The sprinkler system was rendered inoperable by the explosion.		
	Root causes included: 1) Inadequate hazard awareness (polyethylene dust		
	not recognised as combustible material), 2) Inadequate risk assessment		
	(ignition risk, hazardous area classification), 3) Inadequate process hazard		
	analysis (consequences of comply with relevant design codes and fire seferic		
	standards), 5) Inadequate communication (combustible dust hazard not		
	communicated to employees), 6) Inadequate training and procedures		
	(control of combustible dust hazards).		
Lessons Learned	1) A full combustibility assessment should be carried out on all fine powders		
	even if the MSDS does not indicate a combustibility risk.		
	2) HVAC (comfort air) systems are capable of drawing fine dust through		
	suspended ceilings and into air ducts operating at negative pressure.		
	3) Housekeeping (cleaning) activity should include all areas of a facility, not		
	Just the main manufacturing process area.		
	explosion with potential for major injuries fatalities and facility destruction		
More Information	1) "Dust Explosion" US Chemical Safety and Hazard Investigation Board		
wore information	Report No. 2003-07-I-NC (2004)		
	2) "Combustible Dust Explosion", US Chemical Safety and Hazard		
	Investigation Board, Safety Digest, April 2018.		
	3) "Kinston Dust Explosion", Q. A. Baker & M. Kolbe, Proceedings of the 5 th		
	International Seminar on Fire and Explosion Hazards, April 2007.		
	4) HSG103: "Safe Handling of Combustible Dusts – Precautions against		
	Explosions", UK Health & Safety Executive, ISBN 978 0 7176 2726 4 (2003).		
	5) BS EN 60079 Part 10-2: "Explosive Atmospheres – Classification of Areas		
Inductor Costan	_ – Com	Broccos Tures, BSI (2013).
Dharmacoutical		Pubber compounding	Dust Explosion
Not equipment related		Not applicable	Not applicable